A 1				۱	Form C- 104
<u>i</u>		TT	OIL CONSERVATION COM		The second second second second
1-11			Santa Fe, New Mexico		RECEIVED
114	to the second process of the second s	<u>ب</u> ال	EQUEST FOR (OIL)-(GAS) A	LLOWARLE	
	and the second designed and the se				1 L & 1/382
It is nec	essary the	t this	form be submitted by the oper	rator before a	initial allowable
will be a	ssigned to	any co	mpleted oil or gas well. For Transport Oil) will not be ar	rm U-110 (Cer oproved until	orm Catoo a stabed
ance and . with the	<u>Autnorizat</u> Commission	n. Form	C-104 is to be submitted in	triplicate to	the office to which and the
Form C-10	1 was sent	. Two	copies will be retained there	e and the othe	r submitted to the
Proration	Office, H	lobbs, N	ew Mexico. The allowable wil	ll be assigned	effective 7:00 a.m.
on date o	f completi	ion, pro	vided completion report is f be that date in the case of g	an oil well wh	en oil is delivered
into the	stock tank	cs. Gas	must be reported on 15.025 I	P.B. at 60 ⁰ F	ahrenheit.
K	ermit, Tex	Plac	e	Jebruary Dat	10, 1735
		•	See 3 Kr & Law		
WE ARE HE	REBY REQU	ESTING A	N ALLOWABLE FOR A WELL KNOWN		
Magnol	la Patrola	erm Comp	ry Jack Merkhan Well ! Lease	No	L 1/4 SE 1/4
C	ompany or	Operato	r Lease		
section	11 . т.	,	R, N.M.P.MBough	Pool	County
Please in	dicate loo	cation:	Elevation 4145 Spudde	d_11-21-51 Com	pleted2_12=52
·····			Total Depth	P.B	
			Top Oil/Gas Pay 9706		
			Initial Production Test: Pu	mpFlow_	351.08 (BOPD OR CU. FT.)
			Based on 351.08 Bbls. Oil in		
			Method of Test (Pitot, gauge	•	
			Size of choke in inches		
			Tubing (Size)		9715 Feet
			Pressures: Tubing 1050-115		
	6601		Gas/0il Ratio		
	660			Perforations:	
Unit let	ter:0		None		
			Acid Record:	Show of	Oil,Gas and water
Casing &	Cementing	Record	Gals to		
Size	Feet	Sax	Gals to		
			Gals to		
10 3/4*	467	450	Shooting Record.		
			Mana Ots to	s/	
7 5/8*	1258	2175	Ncme Qts to Qts to	S/	
7 5/8*		2175	Nome Qts to Qts to	<u>\$/</u> <u>\$/</u>	
5 1/2"	4258 5581'	2175 1850	Qts to	S/ S/ S/	
	5581'		Qts to Qts to Natural Production Test:	S/ S/ Pumpir	ngFlowing
5 1/2"	5581 1 4124-		Qts to	S/ S/ Pumpir	ngFlowing
5 1/2" liner	5581' <u>4124</u> 9705	1850	Qts to Qts to Natural Production Test:	S/ S/ Pumpir Pumpir	ngFlowing
5 1/2" liner	5581 4124 9705 ndicate be	1850	Qtsto Qtsto Natural Production Test: Test after acid or shot: mation Tops(in conformance wi	S/S/ S/Pumpir Pumpir Pumpir .th geographics	ngFlowing
5 1/2" liner	5581' 4124- 9705 ndicate be So	1850 low Form utheast	Qtsto Qtsto Natural Production Test: Test after acid or shot: mation Tops(in conformance wi ern New Mexico	S/S/	ngFlowing ngFlowing al section of state): tern New Mexico
5 1/2° liner Please in T. Anhy	55811 4124- 9705 ndicate be So	1850 low Form utheaste	Qtsto Qtsto Natural Production Test: Test after acid or shot: mation Tops(in conformance wi ern New Mexico T. Devonian	S/ S/ Pumpir Pumpir th geographics Northwest T. Ojo Alar	ngFlowing ngFlowing al section of state): tern New Mexico
5 1/2° liner Please in T. Anhy_ T. Salt_ B. Salt	55811 4124- 9705 ndicate be So 21	1850 low Form utheaste	Qtsto Qtsto Natural Production Test: Test after acid or shot: mation Tops(in conformance wi ern New Mexico T. Devonian T. Silurian T. Montoya	S/ S/ Pumpir Pumpir Pumpir Pumpir Pumpir T. Northwest T. Ojo Alar T. Kirtland T. Farming	ngFlowing ngFlowing al section of state): tern New Mexico mo d-Fruitland ton
5 1/2" liner Please in T. Anhy _ T. Salt _ B. Salt _ T. Yates	55811 4124- 9705 ndicate be: So 21	1850 low Form utheaster 190	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Interference with the shot of the sh	S/ S/ Pumpir T. Qjo Alar T. Farming T. Pictured	ngFlowing ngFlowing al section of state): tern New Mexico mo d-Fruitland ton i Cliffs
5 1/2" 11ner Please in T. Anhy _ T. Salt _ B. Salt _ T. Yates T. 7 Rive	5581' 4124- 9705 ndicate be So 21 	1850 low Form utheaste 190	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Interface mation Tops(in conformance will ern New Mexico T. Devonian T. Silurian T. Silurian T. Simpson T. McKee	S/ S/ Pumpir T. Ojo Alar T. Farming T. Pictured T. Cliff Ho	ngFlowing ngFlowing al section of state): tern New Mexico mo d-Fruitland ton i Cliffs
5 1/2" 11ner Please in T. Anhy _ T. Salt _ B. Salt _ T. Yates T. 7 Rive T. Queen	5581' 4124- 9705 odicate be So 21 22 ers	1850 low Formutheaster 190	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Interface mation Tops(in conformance will ern New Mexico T. Devonian T. Silurian T. Montoya T. McKee T. Ellenburger	S/ S/ S/ Pumpir Pumpir Pumpir Pumpir T. Ojo Alar T. Ojo Alar T. Kirtland T. Farming T. Pictured T. Cliff Ho T. Menefee	ngFlowing ngFlowing al section of state): tern New Mexico mo d-Fruitland ton i Cliffs
5 1/2" 11 mmr Please in T. Anhy _ T. Salt B. Salt T. Yates T. 7 Rive T. Queen T. Graybu	5581' 4124- 9705 ndicate be So 21 	1850 low Formutheaster 190	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Interface with the shot of the shot	S/ S/ S/ Pumpir Pumpir Pumpir Pumpir Pumpir T. Ojo Alar T. Ojo Alar T. Kirtland T. Farming T. Pictured T. Cliff Ho T. Menefee T. Point Lo	ngFlowing ngFlowing al section of state): tern New Mexico no d-Fruitland ton i Cliffs ouse
5 1/2" 11mm Please in T. Anhy _ T. Salt _ B. Salt _ T. Yates T. Yates T. Queen T. Graybu T. San An T. Glorio	5581' 4124- 9705 ndicate be So 21 24 ers 17g ndres 44 eta 5	1850 low Formutheaster 190 190	Qts to Qts to Natural Production Test:	S/ S/ Pumpir Pumpir Pumpir Pumpir Pumpir Pumpir T. Ojo Alar T. Ojo Alar T. Kirtland T. Farming T. Pictured T. Cliff Hd T. Menefee T. Point Ld T. Mancos T. Dakota	ngFlowing ngFlowing al section of state): tern New Mexico mo d-Fruitland ton i Cliffs pokout
5 1/2" 11 mm Please in T. Anhy _ T. Salt _ B. Salt _ T. Yates T. Yates T. Queen T. Graybu T. San An T. Glorid T. Drinka	5581' 4124- 9705 Adicate be: So 21 24 ers arg 44 eta 54 ard	1850 low Formutheaster 190 790	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Imation Tops(in conformance with acid or shot: mation Tops(in conformance with acid or shot: Imation Tops(in conformance with acid or shot: mation Tops(in conformance with acid or shot: Imation Tops(in conformance with acid or shot: mation Tops(in conformance with acid or shot: Imation Tops(in conformance with acid or shot: T. Devonian Imation Tops(in conformance with acid or shot: T. Devonian Imation Tops(in conformance with acid or shot: T. Devonian Imation Tops(in conformance with acid or shot: T. Silurian Imation Tops(in conformance with acid or shot: T. Montoya Imation Tops(in conformance with acid or shot: T. Simpson Imation Tops(in conformance with acid or shot: T. Granite Imation Tops(in conformance with acid or shot: T. Imation Imation Tops(in conformance with acid or shot: T. Granite Imation Tops(in conformance with acid or shot: T. Imation Imation Tops(in conformance with acid or shot: T. Granite Imation Tops(in conformance with acid or shot: T. Imation Imation Tops(in conformace with acid or shot:	S/S/S/	ngFlowing ngFlowing al section of state): tern New Mexico bo d-Fruitland i Cliffs pokout
5 1/2" 11mm Please in T. Anhy _ T. Salt _ B. Salt _ T. Yates T. Yates T. Queen T. Graybu T. San An T. Glorio T. Drinka T. Tubbs	5581' 4124- 9705 ndicate be So 21 24 ers 17g eta 44 eta 54 ard 6	1850 low Formutheaster 190 790	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Integer mation Tops(in conformance will ern New Mexico T. Devonian T. Silurian T. Simpson T. Simpson T. Granite T. Granite T. T. T. Granite	S/	ngFlowing ngFlowing al section of state): tern New Mexico bo d-Fruitland i Cliffs pokout
5 1/2"11mmPlease inT. SaltB. SaltT. YatesT. 7 RiveT. QueenT. GraybeT. GlorieT. GlorieT. TubbsT. AboT. Penn	5581' <u>4124-</u> 9705 Adicate be So 21 22 ers 17g eta 54 ard 54 54 54 54 54 54 54 54 54 54	1850 1 ow Formutheaster 190 790 790 790 790 790 790 790 7	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will r. Devonian Ination Tops(in conformance will r. Sillurian Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will be in conf	S/	ngFlowing ngFlowing ngFlowing al section of state): tern New Mexico no d-Fruitland ton t Cliffs pokout n
5 1/2*11mmPlease inT. SaltB. SaltT. YatesT. 7 RiveT. QueenT. GraybeT. GlorieT. BlorieT. DrinkaT. AboT. Penn	5581' 4124- 9705 ndicate be So 21 22 ers arg eta 54 64 7	1850 1 ow Formutheaster 190 790 790 790 790 790 790 790 7	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will r. Devonian Ination Tops(in conformance will r. Sillurian Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will be in conf	S/	ngFlowing ngFlowing al section of state): tern New Mexico no d-Fruitland i Cliffs pokout
5 1/2"11mmPlease inT. Anhy	5581' 4124- 9705 Adicate be So 21 22 ers arg ard 44 64 7 84 64 7 84 64 7 84 64 7 84 64 7 84 84 84 84 84 84 84 84 84 84	1850 1 ow Formutheaster 190 790 790 790 790 790 790 790 7	Qts to Qts to Natural Production Test: Test after acid or shot: Test after acid or shot: Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will mation Tops(in conformance will Ination Tops(in conformance will r. Devonian Ination Tops(in conformance will r. Sillurian Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will r. Simpson Ination Tops(in conformance will be in conf	S/	ngFlowing ngFlowing ngFlowing al section of state): tern New Mexico no d-Fruitland ton t Cliffs pokout n

ين السيم ما تربع ي

.

-

.

Date first oil run to tanks or gas to pipe line: 2-15-52
Pipe line taking oil or gas: Magnolia Pipe Line Company
Remarks: New Vell - Original Filing
· · · ·
Company or Operator
Company or Operator
By: Magolulfalle
Signāture
Position: District Superintendent
Send communications regarding well to:
Name: Magnolia Petroleum Company
Address: Box 727, Kernet, Texas
APPROVED 2 - 18, 1952
OIL CONSERVATION COMMISSION
By: Noy yucheacyk
Di I COLL I WOW W - VAT-

z, (,

-

I

Title:_

.

4

.

•

.

3 HM OCC 1 File 1 Div Supt 1 Div Engr 1 Dist Engr 1 Gas Dept 1 Geo