UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	5. LEASE NM-0-149958
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
1 oil gas	8. FARM OR LEASE NAME Federal 13
well well other	9. WELL NO.
2. NAME OF OPERATOR Coquina Oil Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Bough Permo Penn.
P. O. Drawer 2960, Midland, Texas 79702	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit D 660' FML & 660' FWL, Sec. 13	AREA Sec. 13, T9S, R35E
AT SURFACE:  AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: Same	Lea New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	GL 4120
TEST WATER SHUT-OFF	
SHOOT OR ACIDIZE	1979
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	W MEXICO
ABANDON*	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones portions.	
to wat doping for an markers and zones pertinent	. to this work.)*
On July 2, 1977, ran tubing to 8,072'. Spotted	50 sxs cement on top of fish at
8,072'. Pulled 35 stands of tubing. Then tagg the hole with the tubing. Put on 7" wiper plug	and nushed to 8 072! with tubing
sported so sxs on top. Top of plug at $/.300$ ';	Pumped mud : Spotted 35 eye plug
at 5,500. Pumped mud. Spotted 50 sxs plug at 4 sxs plug at 2,300', pumped mud. Spotted 10 sx a	.600' Pumped mid Snotted 35
marker and cleaned location. Plugging completed	17-5-77. Alagain and note
	$\frac{d^2}{dt} = \frac{d^2}{dt} \left[ \frac{d^2}{dt} \left[ \frac{d^2}{dt} \right] + \frac{d^2}{dt} \left[ \frac{d^2}{dt} \left[ \frac{d^2}{dt} \left[ \frac{d^2}{dt} \right] + \frac{d^2}{dt} \left[ \frac{d^2}{dt} \left[ \frac{d^2}{dt$
·	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
8. I hereby certify that the foregoing is true and correct	
IGNED TITLE ASS'T Production	on Mgr. March 21, 1978
(This space for Federal or State office use)	
PPROVED BY	APPROVED
ONDITIONS OF APPROVAL, IF ANY:	- DATE

ACTING DISTRICT ENGINEER

procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office. General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local per Federal office for specific instructions

fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of we above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of we

생 말 3 0 GPO: 1976 O - 214년14월 3

ЫĨ

.∘oʻ ≓ë∉

. 15 1

Feder Feder

and/or State offices.

-, g,₩ar yanuzad

present significant date well site between and

below,

355081 OL

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal

proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with

conditioned for final inspection looking to approval of the abandonment

State or Federal office for specific instructions.

In addition, such

NECH OCICAL SUPVEY DEPARTMENT OF THE INTERIOR mailed alvida

ŗ.