

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature of Notice by Checkin		
NOTICE OF INTENTION O CHANGE PLANS		Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
otice of Intention OPLUG WELL	x	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
otice of Intention o Squeeze		Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate		Notice of Intention (Other)	Notice of Intention (Other)	
IL CONSERVATION COMMIS ANTA FE, NEW MEXICO entlemen:	SION	Hobbs, New Hexic	o Desember 28,	1955
		certain work as described below at the		
Gulf Oil Corpe	ration	John Allen	Well No 1 in	<u>G</u>
NE 1/ NV 1/ of Sec	14	, т. 9-S , R 35-E N		(Omt)
(40-acre Subdivision)		The state of the s	RFM1.,	
Since production was	orrom i	DETAILS OF PROPOSED PLA INSTRUCTIONS IN THE RULES A stained in the Queen Zone,	ND REGULATIONS)	and
Since production was abandon subject well 1. Spot cemen 2. Spot heavy	net ob as fol- t in 9- mud to ement p	nstructions in the Rules A stained in the Queen Zone, lews: -5/8" easing to a point ab -50'. lug to surface. e marker.	nd regulations) it is preposed to plug	
Since production was abandon subject well 1. Spot cemen 2. Spot heavy 3. Spot 50' c 4. Erect 4" x	net ob as fol- t in 9- mud to ement p	nstructions in the Rules A stained in the Queen Zone, lews: -5/8" easing to a point ab -50'. lug to surface. e marker.	nd regulations) it is preposed to plug	
Since production was abandon subject well 1. Spot cemen 2. Spot heavy 3. Spot 50' c 4. Erect 4" x Offset lesses have	net ob as fol- t in 9- mud to ement p	nstructions in the Rules A stained in the Queen Zone, lews: -5/8" easing to a point ab -50'. lug to surface. e marker.	nd REGULATIONS) it is preposed to plug ove 3500' (top of perfor	
Since production was abandon subject well 1. Spot cemen 2. Spot heavy 3. Spot 50' c 4. Erect 4" x Offset lesses have	net ob. as foliat in 9- mud to ement pi 4' pip	tained in the Queen Zone, lews: 5/8" easing to a point ab 50'. lug to surface. e marker. tified. By	nd REGULATIONS) it is preposed to plug ove 3500' (top of perfor	rations).
Since production was abandon subject well 1. Spot cemen 2. Spot heavy 3. Spot 50' e 4. Erect 4" x Offset lessees have Approved DIL CONSERVATION COMMIS	net ob. as foliat in 9- mud to ement pi 4' pip	tained in the Queen Zone, lews: 5/8" easing to a point ab 50'. lug to surface. e marker. tified. By	Company or Operation Company or Operation	rations).
Since production was abandon subject well 1. Spot cemen 2. Spot heavy 3. Spot 50' c 4. Erect 4" x Offset lessees have	net ob. as foliat in 9- mud to ement pi 4' pip	tained in the Queen Zone, lews: 5/8" easing to a point ab 50'. lug to surface. e marker. tified. By	it is preposed to plug ove 3500' (top of perfor Company or Operation Company or Operator Letter Area Supt. of P Send Communications regarding well	rations).