

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

January 17, 1957

Doolin Drlg. Co.
2611 Country Club Drive
Midland, Tex.

Gentlemen:

Mr. W. E. Gressett, Oil & Gas Inspector for the Commission has made an inspection of the location for your Vickers State No. 1 in Unit O of Section 8, T-11-S, R-35-E and has found that the legal description of the location has not been placed on the marker. This description should include the quarter quarter section.

Please advise this office when this has been done so that a final inspection may be made and your Report of Final Plugging approved without further delay.

Yours very truly,

OIL CONSERVATION COMMISSION

R. F. Montgomery
Proration Manager

MC

C
O
P
Y