

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-85

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Leo Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05006-0001
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	LC-1796-1

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name State AR
2. Name of Operator Lynx Petroleum Consultants, Inc.	
3. Address of Operator P. O. Box 1979, Hobbs, NM 88241	8. Well No. 2
4. Well Location Unit Letter L : 990 Feet From The West Line and 1650 Feet From The South Line Section 2 Township 11S Range 37E NMPM Lea County	9. Pool name or Wildcat Echols (Devonian)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3953' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/13/91 MIRU.

4/15/91 Pull rods and tubing and lay down. Run tubing back in hole to 4080'. Circulate mud. Spot 40 sxs cement from 4080-3880'. Pull tubing.

4/16/91 Run in hole. Tag plug at 3880'. Pull tubing to 2200'. Spot 25 sxs cement from 2200-2100'. Pull tubing to 287'. Spot 25 sxs cement from 287-187'. Pull to 50' from surface. Circulate 10 sxs cement to surface. Cut off wellhead. Install marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marc L. Wise TITLE President DATE 2/4/92
TYPE OR PRINT NAME Marc L. Wise TELEPHONE NO 392-6950

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS DATE FEB 10 1992