

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
FILE	
DATE	
FIELD OFFICE	
TRANSPORTER	OIL
	GAS
REGISTRATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION **FORM C-103**
MISCELLANEOUS REPORTS ON WELLS **HOBBS OFFICE 0 (Rev. 3-55)**

(Submit to appropriate District Office as per Commission Rule 1106)

JAN 8 3 54 PM '64

Name of Company Redfern Development Corporation				Address P. O. Box 1747, Midland, Texas			
Lease Sunray - State	Well No. 1	Unit Letter M	Section 11	Township 10S	Range 32E		
Date Work Performed 1-3-64	Pool Undesignated				County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- | | | |
|--|--|---|
| <input type="checkbox"/> Beginning Drilling Operations | <input checked="" type="checkbox"/> Casing Test and Cement Job | <input type="checkbox"/> Other (Explain): |
| <input type="checkbox"/> Plugging | <input type="checkbox"/> Remedial Work | |


Detailed account of work done, nature and quantity of materials used, and results obtained.

Drilled from 4160' to 4410' with 7-7/8" bit. Ran Gamma Ray - Acoustilog and laterolog. Ran 4403' of 4 1/2", 9.5# casing and cemented with 90 sacks of latex and 100 sacks of regular neat cement. W.O.C. 24 hours. Casing tested to 1000#. Plug back total depth after cement 4380.5'.

Witnessed by Frank W. Podpechan		Position Geologist		Company Redfern Development Corporation		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	T D	P B T D		Producing Interval	Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter	Oil String Depth	
Perforated Interval(s)						
Open Hole Interval			Producing Formation(s)			
RESULTS OF WORKOVER						
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name Frank W. Podpechan
Title	Position Geologist
Date JAN 3 1964	Company Redfern Development Corporation