

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. CG-961
7. Unit Agreement Name
8. Farm or Lease Name HUMBLE "C" STATE
9. Well No. 1
10. Field and Pool, or Wildcat INDE (PUBLIC PTN.)
12. County LEA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator J. C. BARNES OIL CO.
3. Address of Operator P.O. BOX-505, MIDLAND, TEXAS 79701
4. Location of Well UNIT LETTER 1980' FEET FROM THE SOUTH LINE AND 660' FEET FROM THE WEST LINE, SECTION 34 TOWNSHIP 10-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4194'

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. SET A CIRP W/20' CEMENT AT 9000'.
2. SPOT 25 SX CEMENT PLUG AT 4 1/2" CASING STUB AT 6000'.
3. SPOT 25 SX CEMENT PLUG AT TOP OF GLORIETTA AT 5290'.
4. SPOT 25 SX CEMENT PLUG AT 7 5/8" CASING SHOE AT 4000'.
5. SPOT 25 SX CEMENT PLUG AT 7 5/8" CSG. STUB AT 2000'.
6. SPOT 25 SX CEMENT PLUG AT 10 3/4" CSG. SHOE AT 1260'.
7. SPOT 10 SX CEMENT PLUG AT SURFACE W/MARKER.
8. HOLE WILL BE LOADED WITH MUD-LOADED FLUIDS.

All plugs 100' in length

24 hr. notice prior to setting plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. H. Vandenberg TITLE PRODUCTION ACCT. DATE 8-17-72

APPROVED BY Joe D. Ramey DATE AUG 21 1972
CONDITIONS OF APPROVAL, IF ANY: Dist. I, Supv.

RECEIVED

AUG 21 1972

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
OIL CONSERVATION COMM.
HOBBS, N. M.