

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
<b>NM 315</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
3. Address of Operator	9. Well No.
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <b>B</b> FEET FROM THE <b>North</b> LINE AND <b>2130</b> FEET FROM THE <b>East</b> LINE, SECTION <b>10</b> TOWNSHIP <b>11-S</b> RANGE <b>33-E</b> NMPM.	12. County
15. Elevation (Show whether DF, RT, GR, etc.)	
<b>4262' GR</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <b>Clean out &amp; repair collapsed casing</b> <input checked="" type="checkbox"/>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU. Ran free point found: 2-3/8" tubing free @ 7590'; stuck @ 7610'  
2-1/16" tubing free @ 7614'; stuck @ 7618'
  - Ran 1-5/8" DP & broach. Unable to open tubing below 7627'. POH w/ drill pipe & broach.
  - Ran tubing cutter in 2-1/16" tubing & cut off @ 7564'. POH with 2-1/16" tubing.
  - Ran tubing cutter & cut off 2-3/8" tubing @ 7582' and POH.
  - Ran 2-3/8" tubing with 2-1/16" overshot. Unable to clean out below 7450' due to fill coming from parted casing.
  - Pulled 2-3/8" tubing and fishing tools. Ran 2-3/8" tubing.
- Well temporarily abandoned 1-24-73. Preparing to P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	Original Signed By <b>Claude Aubert, Jr.</b>	TITLE	<b>Area Superintendent</b>	DATE	<b>2-14-73</b>
APPROVED BY	Orig. Signed By <b>J. D. Brown</b>	TITLE		DATE	<b>FEB 16 1973</b>
CONDITIONS OF APPROVAL, IF ANY:					