

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM 0450847

6. IF INDIAN, ALLOTTEE, OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FEDERAL "A"

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

BOUGH DEVONIAN

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

13-9-35 NM PM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Dry Hole**

2. NAME OF OPERATOR

Dan American Petroleum Corp.

3. ADDRESS OF OPERATOR

Box 68, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2310 FSL X 2310 FEL, Sec 13 (UNIT J, NW1/4 SE1/4

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, GR, etc.)

4116' R.D.B.

12. COUNTY OR PARISH

LEA

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pursuant to telephone approval of 9-14-65, Mr. A.R. Brown to Mr. J. H. Meek, abandonment of well proposed as follows:

TD-12,103'. No shows of oil or gas. To spot plugs 50 SX - 12103-12009; 50 SX - 10500-10400; 50 SX - 9650-9550; 50 SX - 8000-7900; 50 SX - 6400-6300; 50 SX - IN and OUT of Int. Csg at 4888; 10" at surface and erect P+G Marker. All intervals filled w/ mud. Final cleanup of location to be made and ground restored to contour.

13 3/8" CSA 455 w/400 SX - Circ.
9 7/8" CSA 4888 w/2200 SX - Circ.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supt

DATE

9-16-65

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

SEP 21 1965

A. R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side