DISTRIBUTION		
CANTA EE		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		Elective 1-1=03
U.S.G.S.	UST 13 3 38 PM 'S5	5a. Indicate Type of Lease
LAND OFFICE	33 77 55	State T Fee
OPERATOR		5. State Oil & Gas Lease No.
		09-1020
SLIA	IDRY NOTICES AND REPORTS ON WELLS	mmmmmm
(DO NOT USE THIS FORM FOR	IDRY NOTICES AND REPORTS ON WELLS  PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  ICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
•	(FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL	OTHER. Dry Hole	,, out hyreement Name
Name of Operator		8. Farm or Lease Name
Sunray DI	Oil Company	
. Address of Operator		New Mexico State "BB 9. Well No.
P. O. Box	1416, Rossell, New Mexico	
. Location of Well		10. Field and Pool, or Wildcat
<b>G</b>	1980 # 2017	i '
UNIT LETTER	1980 FEET FROM THE LINE AND FEET FROM	Wildest
K	9 08 300	
THELINE, SE	CCTION TOWNSHIP RANGE 328 NMPM	
	(C) 1.4 DE DE CD	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	1/1/1/1/1 14450 DP	Lea
Chec	k Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF	INTENTION TO	T REPORT OF:
	0020240211	. KEI OKT OF.
ERFORM REMEDIAL WORK	PLUG AND ABANDON TREMEDIAL WORK	<u>.</u>
EMPORARILY ABANDON		ALTERING CASING
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
ozz sk azyek dasike	CHANGE PLANS CASING TEST AND CEMENT JOB	
		-
OTHER	OTHER	[
-	Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any propos
7. Describe Proposed or Completed work) SEE RULE 1103.  1. Propose to P&A  25 ax 9340-9220 25 sx 4900-4780  2. Install dry hold  3. Fill pits and letter work in the control of the contro	as follows:  25 sx 8780-8900, 25 sx 8400-8280, 25 sx 7200-708, 25 sx 3611-3431, 10 sx in top of csg.	