Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
District I	Energy, Miner	als and Nat	ural Resources	WELL ADINO	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II	OH GOM		I DII HOLOVI	WELL API NO. 30–0	25-21948
11 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fo. NM 87505				STATE X FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & Gas Lease No. 0G-530	
SUNDRY NOTI	CES AND REPORTS	S ON WELL	S		or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				, Boase Manne	A Sim Figreement Flame,
PROPOSALS.)				STATE	DG .
1. Type of Well: Oil Well Gas Well Other					
2. Name of Operator				8. Well No.	
PRIME OPERATING COMPANY				1	
3. Address of Operator 3300 N. "A", BLDG. ONE, SUITE 238, MIDLAND, TX 79705				9. Pool name or Wildcat BAGLEY, LOWER PENN, NO.	
4. Well Location					water Final Property and the second
11.91 n P	1000 6 46	. Nomb	L 12 1	1000 6 . 6	d 174- U
Unit Letter F :	1980 feet from	the NOT L	h line and	1980feet fro	om the West line
Section 16	Township	11-S R	ange 33-E	NMPM	County LEA
			OR, RKB, RT, GR, etc	2.)	
11 Check A	4297 ppropriate Box to		Jature of Notice	Penart or Other	Data
NOTICE OF IN		marcate is	1	SEQUENT RE	
PERFORM REMEDIAL WORK		ON XX	REMEDIAL WOR		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN	ND 🗆	ABANDONMENT -
OTHER:		 1	OTHER:		
12. Describe proposed or complete	ed operations (Clear	lv state all ne		vive pertinent dates	including estimated date
of starting any proposed work)	SEE RULE 1103.	For Multiple	Completions: Attacl	h wellbore diagram	of proposed completion
or recompilation.	35/				
1. Set CIBP @ 9000° 2. Spot cement plug 3. Spot cement plug 4. Cut off 5 1/2" of	'W/ 20' of ce	ment on	top.		
2. Spot cement plug	from 7292' t	o 7392'	- Tag.		
3. Spot cement plug	from 5070' t	o 5170'.	_		
4. Cut off 5 1/2" (asing @ 3900'	- spot	cement plug f	rom 3950' to	3800'
- 8 5/8" Ca	sing is set @ . from 1800! +	3851'	- 146 - top of colt	71112/202122	.2324253
6. Cut off 8 5/8" of	asing @ 500'.	Spot c	- top or sart ement plug fr	om 550 to 3	150'
- 13 3/8" s	surface casing	is set	@ 400'TAG		1 2000
7. Spot 10 sx plug	@ surface and	weld on	dry hole mar	ketse All	L COOL
				1415 Kr	Hobbs W
				15	OCD 7
				\c <u>\</u>	(1)/
I hereby certify that the information	above is true and cor	nplete to the	best of my knowled	ge and belief 016	87.984
SIGNATURE Comme	Ree L_	TITLE_	AGENT		DATE 4-18-02
Type or print name SAMMY I	REED			Telep	phone No. 915-682-5600
(This space for State use)	7 42	erri, LuiC	SNED RY		
APPPROVED BY	1. A	EV WOMEN	4K	in the second	- DATE
Conditions of approval, if any:	* 7. ·	THELD KEP	RESENTATIVE II/S	TAFF MANAGE	DATE
					MOTIFIED 24
			HOURS PRICE	dr to the Bec Operations fo	NO ME SE 29 12 SINDING SE 29 12 SRITHE C-103
			TO BE APPRO	DEFENDING !	····