

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-585
7. Unit Agreement Name
8. Farm or Lease Name T. P. State
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Lea

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	2. Name of Operator K. K. Amini
3. Address of Operator 816 Bank of the Southwest Building - Midland, Texas	
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>10S</u> RANGE <u>33E</u> NMPM.	
5. Designation (Show whether DP, RT, GR, etc.) 4236.1 GR	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugs set as:

Cast Iron Bridge Plug at 9990' capped with cement
25 sx. at 7212' - 4-1/2" stub
25 sx. at 6620' (Tubb)
25 sx. at 5480' (Glorieta)
25 sx. at 3828' base of 8-5/8"
25 sx at 1520' 8-5/8" stub
25 sx. at 367' (top of (anhydrite)
10 sx. at top of surface casing with marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Norma Johnson TITLE Agent DATE January 8, 1968
APPROVED BY John W. Runyan TITLE _____ DATE _____
CONFIRMATION OF APPROVAL, IF ANY