

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Gulf Oil Corporation

Address of Operator
P. O. Box 670, Hobbs, NM 88240

Location of Well
UNIT LETTER **B** **600** FEET FROM THE **North** LINE AND **1980** FEET FROM
THE **East** LINE, SECTION **15** TOWNSHIP **11-S** RANGE **33-E** NMPM.

15. Elevation (Show whether DF, RT, CR, etc.)
4258' GL

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

7. Unit Agreement Name

6. Form of Lease Name
Lea "HP" State

9. Well No.
1

10. Field and Pool, or Wildcat
Undes San Andres

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5080' PB.

Pull Producing equipment. Set a CIBP at 3750' and cap with 35' cement. Spot abandonment mud from 3715' to 50'. Spot a 50' cement plug from 50' to surface. Install dry hole marker. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *N. B. Sikes, Jr.* TITLE Area Engineer DATE 1-27-78

ORIG. SIGNED BY Jerry Sexton TITLE Dist. 1, Supv. DATE JAN 30 1978

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY: