

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUN 15 11 38 AM '67

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>OG 854</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name <b>None</b>
2. Name of Operator <b>Charles B. Read</b>	8. Farm or Lease Name <b>Apache</b>
3. Address of Operator <b>P. O. Box 2126, Roswell, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>F</b> <b>510</b> FEET FROM THE <b>East</b> LINE AND <b>660</b> FEET FROM THE <b>South</b> LINE, SECTION <b>3</b> TOWNSHIP <b>10S</b> RANGE <b>33E</b> NMPM.	10. Field and Pool, or Wildcat <b>Undesignated</b>
15. Elevation (Show whether DF, RT, CR, etc.)	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded at 11:00 A.M., 5/17/67.

Ran 9 joints 12-3/4", 38# surface casing, set at 365' KB, cemented w/350 sx regular/2% CaCl, cement circulated to surface. Plug down at 12:15 A.M., 5/18/67. WOC 18 hrs. Tested casing w/1000#, no pressure drop, test O.K.

Set 8-5/8", 28# and 32# casing at 3400' w/300 sx Class C Lone Star and 50 sx Lone Star, 2% CaCl. Plug down at 10:30 P.M., 5/23/67. Tested casing w/1000# for 30 mins., no pressure drop, WOC 18 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles B. Read TITLE Operator DATE 6/14/67

APPROVED BY [Signature] TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY