

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Free <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-765	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Read & Stevens, Inc.		Gross
3. Address of Operator		9. Well No.
P.O. Box 2126, Roswell, New Mexico 88201		2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>2130</u> FEET FROM		
THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>10S</u> RANGE <u>33E</u> NMPM.		
11. Elevation (Show whether DF, RT, GR, etc.)		12. County
4193' GR		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/25/72: Plugged and abandoned as follows:

Set bridge plug @ 9500'; capped w/35' of cement.
Loaded hole with mud.
Cut and pulled 5½" casing @ 5976'.
Ran tbg. to set cmt plugs. Found well caved in @ 5507'
Set cmt plugs as follows via tbg:
35 sx. @ 5507' - 5394'
35 sx. @ 5227' - 5114'
35 sx. @ 3933' - 3829'
Cut and pulled 8 5/8" csg. @ 704'
Filled hole with mud
Set 56 sx. @ 744' - 644'
Set 80 sx. @ 403' - 303'
Set 10 sx. @ 10' - 0'
Installed regulation marker. Will notify when ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *A. DeSantis Tucker* TITLE Agent DATE 3/29/72

APPROVED BY *Nathan E. Clegg* TITLE OIL & GAS INSPECTOR DATE SEP 21 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 1952

OIL CONSERVATION COM.
ROBERT H. M.