

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAY 11 11 33 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5353
7. Unit Agreement Name
8. Farm or Lease Name State "D"
9. Well No. 2
10. Field and Pool, or Wildcat Inbe-Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Southern Minerals Corporation
3. Address of Operator P. O. Box 716 - Corpus Christi, Texas 78403
4. Location of Well UNIT LETTER D , 660 FEET FROM THE North LINE AND 510 FEET FROM West LINE, SECTION 8 TOWNSHIP 11-S RANGE 34-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4195.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER Acidize <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

March 29, 1969 - Acidized perforations 9862' to 9870' and open hole 9870' to 9885' with 3,500 gallons 15% HEC Acid and 1,000# of Wax Beads.

Production prior to acidizing:

**Oil : 70 BPD
Water : 18 BPD
Gas : 56 MCFD**

Production after acidizing:

**Oil : 72 BPD
Water : 27 BPD
Gas : 63 MCFD**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.K. Heinrich TITLE Authorized Employee DATE April 29, 1969

APPROVED BY [Signature] TITLE SUPERVISOR OF OPERATIONS DATE 10*
CONDITIONS OF APPROVAL, IF ANY: