

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Roger C. Hanks		8. Farm or Lease Name McGuffin
3. Address of Operator 2100 Wilco Building, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>O</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1830</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>9S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Flying M. Penn South
15. Elevation (Show whether DF, RT, GR, etc.) 4351.4 GR		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-12-70 Recovered 4039' of 5½" csg. and 1004' of 8 5/8" csg. Set the following plugs:
Plug No. 1 - 50 sx. cement set at 9020'.
Plug No. 2 - 25 sx. cement set at 4000'.
Plug No. 3 - 25 sx. cement set at 1000'.
Plug No. 4 - 25 sx. cement set at 300'.
Plug No. 5 - 10 sx. cement set at surface with steel marker.
Location has been cleared of all equipment. Well site is ready for inspection with the exception of some dirt work to be done.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Roger C. Hanks
Wanda Sanders

TITLE Operator

DATE 12-15-70

APPROVED BY John W. Remyer
CONDITIONS OF APPROVAL, IF ANY:

TITLE Geologist

DATE MAR 24 1971

RECEIVED

10 1970

U.S. CONSERVATION COMMISSION
WASHINGTON, D.C.