

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>OG 1502</b>

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <b>Dry</b>	7. Unit Agreement Name <b>None</b>
2. Name of Operator <b>ROGER C. HANKS, [REDACTED]</b>	8. Farm or Lease Name <b>Lowe-State</b>
3. Address of Operator <b>1102 Oil &amp; Gas Building, Wichita Falls, Texas 76301</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>H</b> , <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>2</b> TOWNSHIP <b>9S</b> RANGE <b>32E</b> NMPM.	10. Field and Pool, or Wildcat <b>Undesignated</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4427.5 GL</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-4/5 Moved Hobbs Pipe & Supply rig and equipment on location and rigged up.

11-7/15 Well was plugged and abandoned by placing a 50 sack cement plug at 9024' over perforations (top of Bough "C"); cement plugs of 25 sacks each were then placed at 4365' (stub of 5 1/2"), stub of 8 5/8", bottom of 13 3/8" and a 10 sack plug was placed at surface. Space between all plugs filled with 10# drilling mud and the location was marked with permanent steel marker. Recovered 846.03' of 8 5/8" casing and 4350.05' of 5 1/2" casing. Location will be cleaned and report submitted as soon as weather permits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <b>Roger C. Hanks</b>	TITLE <b>General Partner</b>	DATE <b>12-10-68</b>
APPROVED BY <b>John W. Runyan</b>	TITLE <b>Geologist</b>	DATE <b>12-27-1969</b>
CONDITIONS OF APPROVAL, IF ANY:		