	Form C-103
N 1. OF COPIES RECEIVED	Supersedes Old
DISTRIBUTION	C-102 and C-103 Effective 1-1-65
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	Ener 144 1-1-03
FILE	a. Indicate Type of Lease
U.S.G.S.	State Fee X
LAND OFFICE	5. State Oll 6 Gas Lease No.
OPERATOR	•••
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO GRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT PESERVOIR.	
I. OIL CAS OTHER-	7. Unit Agreement Name
Name of Operator	8. Farm or Lease Name
The Maurice L. Brown Company	Vada "C"
Address of Operator	9. Well No.
Suite 200/Sutton Place Bldg./Wichita, Kansas 67202	3
Suite 2007 Sutton Trace Stuger, storage,	10. Field and Pool, or Wildcat
4. LOCATION OF Well UNIT LETTER B 660 FEET FROM THE NORth LINE AND 1980 FEET FROM	Vada Penn
UNIT LETTER B, 660 FEET FROM THE NOPTH LINE AND 1930 FEET FROM	••••••••••••••••••••••••••••••••••••••
THE East LINE, SECTION 21 TOWNSHIP 9-S RANGE 34-E	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4272' KB	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or C	ther Data
NOTICE OF INTENTION TO: SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	
17. Describe Freposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103.	ng estimated date of starting any propo <mark>sed</mark>
9-20-79 Move in and rigged up PBCP Services, Inc. Went in bit on 2 3/8" tubing. Cleaned out to 1162'. Pull shut down over night at 6:00 p.m.	ι hole with 4 3/4" .ed out of hole and
9-21-79 Moved in T & B Reverse Circulation Equipment. Wer bit to 1162'. Cleaned out 195' to 1357'. Pulled down over night.	it in hole with 4 3/4" one stand and shut

- -

- 9-22-79 Spotted 70 sx. cement at 1357'. Pulled out of hole. Shut down over night.
- Tagged T/C at 1003'. Displaced hole with salt gel mud. Spotted 70 sx. cement at 425'. Laid down tubing. Tagged top of cement with WL at 320'. Spotted 10 sx. cement at surface. Installed dry hole marker. Rigged down PBCP Services, Inc. 9-23-79

14. 1 Hereby certify that the information above is true and complet	te to the best of my knowledge and belief.	
LAM BLOESDECK	District Engineer	LATE 10-5-79
APPROVED BY A. C. Juitsmin	OIL & CAS INSPECTO	DRJUN 27 1980
CONDITIONS OF APPROVAL, IF ANYS		

c'	ONDITIONS	OF	APPHOVAL.	1F	ANY
----	-----------	----	-----------	----	-----