

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-1C1) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Western States Equipment Company		8. Farm or Lease Name Hutcherson Com
3. Address of Operator Route 5 Box 99 Comanche, Texas 76642		9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE NE North LINE AND 1980 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 9-S RANGE 34-E NMPM.		10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR: 4230		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & Abandonment :

Set 35 sack cement Plug above bough C Formation at 9835'

set 40 sack cement Plug at 5100' (Above Glorieta Formation)

Recovered 5100' 4 1/2" casing.

Set 50 Sack cement plug at 4252' (Base of 8 5/8" Casing Shoe)

Set 25 sack cement Plug at 906' (Recovered 906' 8 5/8" Casing)

set 25 sack cement Plug at 400' (base of 11 3/4" casing)

set 10 sack cement Plug in Top of 11 3/4" casing. Welded on 4" pipe 4' above Ground with well location engraved on Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leather T. McClung TITLE Pres, Dent DATE 2-8-74

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: