

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Western States Equipment Company	5. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 1229, Midland, Texas 79701	7. Unit Agreement Name
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 9-S RANGE 34-E NMPM.	8. Farm or Lease Name Hutcherson Com
15. Elevation (Show whether DF, RT, GR, etc.) KB: 4,244 GR: 4,230	9. Well No. 1
	10. Field and Pool, or Wildcat Vada (Penn)
	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSED ABANDONMENT PROCEDURE:

35 sack cement plug above Bough "C" Perforations 9,835-9,844.
Pull 4-1/2" and 8-5/8" casing.
25 sack cement plug at top of 4-1/2" casing stub.
25 sack cement plug at 7,600' above Abo shale - if more than 7,600' of 4-1/2" casing recovered.
35 sack cement plug at 5,100' above Glorieta sand - if more than 5,100' of 4-1/2" casing recovered.
50 sack cement plug at 8-5/8" casing shoe at 4,252'.
25 sack cement plug at 8-5/8" casing stub.
25 sack cement plug at 11-3/4" casing shoe at 400'.
10 sack cement plug in top of 11-3/4" casing.
Weld 4" pipe on top of 11-3/4" casing extending 4' above ground level with well name and location engraved on marker.

NOTE: The above noted operator has taken over this well from The Superior Oil Company, P. O. Box 1900, Midland, Texas 79701.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  Joe Stickney

TITLE Operator-Western States Equip. Co. April 6, 1971

APPROVED BY

SUPERVISOR DISTRICT I

DATE AUG 16 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 13 1971

OIL CONSERVATION COM. M.
HOBBES, N. M.