

New Mexico Oil Conservation Commission  
P. O. Box 1980  
Hobbs, New Mexico

Gentlemen:

Following is a tabulation of the deviation surveys taken on our Pruitt Well No. 2, located in Section 21, T-9-S, R-34-E, Lea County, New Mexico:

1/2°	@	135'	1-1/2°	@	5331'
1/2°	@	370'	1°	@	5580'
1/4°	@	782'	1/4°	@	5950'
1/4°	@	1100'	1/2°	@	6210'
1/4°	@	1400'	1-1/4°	@	6430'
1/4°	@	1645'	3/4°	@	6690'
1/2°	@	1890'	1°	@	6760'
1/2°	@	2198'	1°	@	7048'
1/2°	@	2460'	1/2°	@	7317'
1°	@	2670'	1/4°	@	7544'
3/4°	@	2870'	1/2°	@	7750'
1/4°	@	3070'	1/2°	@	8119'
1/2°	@	3320'	1/4°	@	8370'
3/4°	@	3575'	1/2°	@	8580'
1/4°	@	3825'	3/4°	@	8740'
1/2°	@	4010'	1/2°	@	8946'
3/4°	@	4227'	1-1/4°	@	9170'
1-1/4°	@	4540'	3/4°	@	9367'
1-1/4°	@	4805'	1/2°	@	9674'
1-3/4°	@	4910'	1/2°	@	9826'
1-3/4°	@	5110'	1/2°	@	9838' T. D.

I hereby certify that the information given above is true and correct to the best of my knowledge.

CABOT CORPORATION

By James H. Cabot  
Dist. Prod. Sup't.

Subscribed and sworn to before me this 11th day of December 19 67.

Anna Louise Harris  
(Notary Public, Midland County, Texas)

1. *Chlorophyll a* (Chl *a*)

**Figure 1**

*Journal of Management Studies*, 19(1), 67-80.

1. The first step in the process is to identify the problem. This involves gathering information about the situation and understanding the needs of the stakeholders involved.