

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-26	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Paloma Operating Co.	8. Farm or Lease Name Lea "OG" STATE
3. Address of Operator P. O. Box 3578, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>9</u> TOWNSHIP <u>11S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat N. Bagley Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4288' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- April 1st commenced operations, pulled out approx. 7530' 2-3/8" tubing
- Went in w/impression block and wireline, then went in w/workstring & mill, came out w/approx. 5' rod & 2' tubing
- Went in w/overshot-came out w/approx. 410' rods & approx. 3' tubing
- Ran impression block, came out, went in w/mill, milled for 2 days, went in w/overshot, grabbed top of tubing, were unable to unseat tubing anchor
- Continued to mill & fish for 9 more days, rig down & moved rig - ceased operations 4/15/88

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. E. McCall TITLE President DATE 4/29/88

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE MAY 3 - 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAY 2 1988
OCD
HOBBS OFFICE