

COPIES RECEIVED		
TRIBUTION		
FE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tipperary Oil & Gas Corporation	8. Farm or Lease Name Bess
3. Address of Operator P.O. Box 3179, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>20</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Will-vent North Bagley Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4308' KB	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug & abandon as follows:

Spot 100 sx plug @ 8000' in 4½" csg.
Cut & pull 4½" csg. from approx 4000'
Spot 50 sx @ top of 4½" csg.
Spot 50 sx @ 8 5/8" csg @ 3700'
Cut 8 5/8" @ 1000'
Spot 100' plug @ top of 8 5/8" csg.
Spot 100' plug @ 13 3/8" csg shoe.
Spot 10' plug @ surface w/regulation marker
Clear & level location

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED William H. Mark TITLE Petroleum Engineer DATE 9-30-77

APPROVED BY John R. Ryan TITLE Geologist DATE 10/1/77
CONDITIONS OF APPROVAL, IF ANY: Expires 4/3/78

1944

31216
OIL CONSERVATION DISTRICT
HOBBS, N. M.