

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator MIDWEST OIL CORPORATION		8. Farm or Lease Name Roy Epperson
3. Address of Operator 1500 Wilco Building Midland, Texas 79701		9. Well No. 2
4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>510</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>11S</u> RANGE <u>33E</u> N.M.P.M.		10. Field and Pool, or Wildcat Inbe (Permo Penn)
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug Back

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-15-73 Set CIBP @9700' w/3 sx cmt on top. Perf w/3½ glass jet (.49 size) @9194-9200 & 9202-04 w/2SPF.

11-16-73 Ran 290 jts. 2-3/8" tbq. w/pkr & SN to 9150'. Spot 1000 gals 15% NE acid w/13 gals NE agent & 1 gal Hal-50 over perms.

11-28-73 Pump 4000 gals 20% retarded acid w/4 gals inhibitor, 1 gal I-11 inhibitor & 5 ball sealers. Treat press max 4800, min 3800. AIR 2.8 BPM.

12-4-73 Waiting on pumping equipment.

1-5-74 Ran pump

1-12-74 Put on pump

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bonnie Husband TITLE Production Clerk DATE 1-16-74

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

BH:nw 1-17-74