

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-5085	

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
BTA Oil Producers		Somico 682 Ltd.	
3. Address of Operator		9. Well No.	
104 South Pecos, Midland, Texas 79701		1	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER "C" 660 FEET FROM THE North LINE AND 1980 FEET FROM		Vada-Penn	
THE West LINE, SECTION 20 TOWNSHIP 10S RANGE 34-E NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
4230 GL		Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & abandoned as follows:

Set CIBP @ 9850' w/2 sx cmt on top  
Cut & pulled 4½" csg @ 8240'  
25 sx @ 8240 (4½" stub)  
25 sx @ 5500' (Glorietta)  
25 sx @ 3820' (8-5/8" shoe)  
Cut & Pulled 8-5/8" csg @ 1316'  
25 sx @ 1316' (8-5/8" stub)  
25 sx @ 367 (12-3/4" shoe)  
10 sx @ surface  
Installed dry hole marker per NMOCC regulations  
Plugged & abandoned 10-7-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. D. Boyce</u>	TITLE <u>Production Clerk</u>	DATE <u>10/22/71</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		