

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30025-22437

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.
PUN 18451 934329

7. Lease Name or Unit Agreement Name
Dessie Sawyer

8. Well No.
2
9. Pool name or Wildcat
Crossroads, Siluro Dev

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Baxter, Kelly H.

3. Address of Operator
P. O. Box 11193, Midland, TX 79702

4. Well Location
Unit Letter K : 2310 Feet From The South Line and 2310 Feet From The West Line

Section 27 Township 9S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Well Plugged and Abandoned ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in rig, install BOP, pick up and tally 2 3/8" tubing, run in hole to 4647, spot 60 sacks of cement, pull tubing up, wait on cement, tag cement plug at 4432, pull tubing up to 4175', spot 60 sacks of cement, pull tubing up hole.
Tag cement at 3985', pull tubing to 1800', spot 60 sacks of cement from 1800-1600, pull tubing to 60', circulate 15 sacks of cement to surface, cut off wellhead, install marker, fill casing and cellar with cement, rig down, move off location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. Johnston TITLE Agent DATE 2/23/93
TYPE OR PRINT NAME L. Johnston TELEPHONE NO. 915-682-549

JAN 13 2003

(This space for State Use)

APPROVED BY

Billy E. Probert

DATE

CONDITIONS OF APPROVAL, IF ANY:

COMPLIANCE OFFICER