

## NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-5059

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
The Maurice L. Brown Company	Vada State
3. Address of Operator	9. Well No.
Suite 200/Sutton Place Bldg./Wichita, Kansas 67202	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>H</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1830</u> FEET FROM	Vada Penn
THE <u>North</u> LINE, SECTION <u>16</u> TOWNSHIP <u>9-S</u> RANGE <u>34-E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4267' KB	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up PBCP Services, Inc.
2. Set cast iron bridge plug at 9553' (50' above Bough "A" perforations) in 4½" casing from 9603' to 9607'.
3. Dump 3 sacks cement on top of bridge plug to form 35' plug using dump bailer.
4. Displace hole through tubing with mud laden fluid.
5. Salvage 4½" casing from free point anticipated to be at 5200' depth.
6. Spot 35 sx. cement through tubing at 50' below 4½" casing stub.
7. Tag top of cement.
8. Spot 35 sx. cement through tubing at 4050' depth to form 100' plug across 8 5/8" casing shoe at 4000' depth.
9. Tag top of cement.
10. Spot 35 sx. cement through tubing at 2150' depth to form 100' plug inside 8 5/8" casing across top of salt section.
11. Salvage 8 5/8" casing from free point anticipated to be at 1000' depth.
12. Spot 70 sx. cement plug from 50' below 8 5/8" casing stub.
13. Tag top of cement.
14. Spot 70 sx. cement plug at 522' depth to form 100' plug across 11 3/4" casing shoe at 472' depth.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. J. Groesbeck TITLE District Engineer DATE 9-26-79

APPROVED BY John R. Ryan TITLE Geologist DATE OCT - 1 1979

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-5059	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
The Maurice L. Brown Company		Vada State
3. Address of Operator		9. Well No.
Suite 200/Sutton Place Bldg./Wichita, Kansas 67202		2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>H</u> , <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1830</u> FEET FROM		Vada Penn
THE <u>North</u> LINE, SECTION <u>16</u> TOWNSHIP <u>9-S</u> RANGE <u>34-E</u> N.M.P.M.		
15. Elevation (Show whether DF, RT, CR, etc.)		12. County
4267' KB		Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

15. Tag top of cement.
16. Spot 10 sx. cement plug inside 11 3/4" casing at surface and erect dry hole marker.
17. Rig down casing pulling rig.
18. Fill cellar and pit. Clean and level location.

THE COMMISSION MUST BE NOTIFIED  
24 HOURS PRIOR TO COMMENCING WORK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. Groesbeck TITLE District Engineer DATE 9-26-79

APPROVED BY John Runya TITLE Geologist DATE OCT -1 1979

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 28 1979

O.C.D. HOBBS, OFFICE