NO. OF COPIES RECEIVED		
DISTRIBUTION	<del> </del>	Form C-103 Supersedes Old
DISTRIBUTION		C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE	<del></del>	State X Fee
OPERATOR		5. State Oil & Gas Lease No.
·		K 3983
	SUNDRY NOTICES AND REPORTS ON WELLS  ORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIP.  "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL A GAS	L OTHER.	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Major, Giebel &	Forster	Nine Ranch, Inc. State
3. Address of Operator		9. Well No.
1126 Vaughn Buile	ding, Midland, Texas 79701	5
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	1980 FEET FROM THE South LINE AND 2130 FEET FROM	Undesignated
	22 10-S 33-E	
THE LOSL	LINE, SECTION TOWNSHIP RANGE NMP	w.(111111111111111111111111111111111111
	15, Elevation (Show whether DF, RT, GR, etc.)	12. County
	4203' GL	Lea
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER	PLUG AND ABANDON REMEDIAL WORK  COMMENCE DRILLING OPNS.  CHANGE PLANS  OTHER	ALTERING CASING  PLUG AND ABANDONMENT
17. Describe Proposed or Co work) SEE RULE 1 103.	ompleted Operations (Clearly state all pertinent details, and give pertinent dates, including	ng estimated date of starting any proposed
4/19/68 Spud	dded well at 2:30 a.m. Drilled 17 1/2" hole to 360'.	Cemented 12 3/4"
4/19/68 Spud 33.3	dded well at 2:30 a.m. Drilled 17 1/2" hole to 360'. 8# H-40 csg w/350 sx cement. Plug down at 3:30 p.m	Cemented 12 3/4" n. Cement circulated.WOC
4/19/68 Spud 33.3 4/20/68 WOC	dded well at 2:30 a.m. Drilled 17 1/2" hole to 360'. 8# H-40 csg w/350 sx cement. Plug down at 3:30 p.m C. Tested csg w/500 psi. OK. Started drilling 11" ho	Cemented 12 3/4" n. Cement circulated.WOCole at 9:30 p.m.
4/19/68 Spud 33.3 4/20/68 WOC 4/25/68 Drill	dded well at 2:30 a.m. Drilled 17 1/2" hole to 360'. 8# H-40 csg w/350 sx cement. Plug down at 3:30 p.m. Tested csg w/500 psi. OK. Started drilling 11" hole to 3900'. Cemented 8 5/8" 28# & 32# J-9	Cemented 12 3/4" n. Cement circulated.WOCole at 9:30 p.m.
4/19/68 Spud 33.3 4/20/68 WOC 4/25/68 Drill Plug	dded well at 2:30 a.m. Drilled 17 1/2" hole to 360'. 8# H-40 csg w/350 sx cement. Plug down at 3:30 p.m. Tested csg w/500 psi. OK. Started drilling 11" hole to 3900'. Cemented 8 5/8" 28# & 32# J-9 down at 8:00 a.m. WOC.	Cemented 12 3/4"  n. Cement circulated.WOCole at 9:30 p.m.  55 csg w/400 sx cement.
4/19/68 Spud 33.3 4/20/68 WOC 4/25/68 Drill Plug	dded well at 2:30 a.m. Drilled 17 1/2" hole to 360'. 8# H-40 csg w/350 sx cement. Plug down at 3:30 p.m. Tested csg w/500 psi. OK. Started drilling 11" hole to 3900'. Cemented 8 5/8" 28# & 32# J-9	Cemented 12 3/4"  n. Cement circulated.WOCole at 9:30 p.m.  55 csg w/400 sx cement.

TITLE Partner

DATE April 26, 1968

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.