NO. OF COPIES RECEIVED		
DISTRIBUTION	1	Form C-103 Supersedes Old
SANTA FE		C-102 and C-103
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE	4	State Fee X
OPERATOR		5. State Oil & Gas Lease No.
	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	TION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)	
		7. Unit Agreement Name
WELL WELL	other- Dry & bandon	
2. Name of Operator		8. Farm or Lease Name
Lario Oil & Gas	5 Company	Yeager ^H A ^H
3. Address of Operator		9. Well No.
Box 1209 Odess	sa, Texas 79760	1
4. Location of Well		10. Field and Pool, or Wildcat
à 66		
UNIT LETTER A	D FEET FROM THE North LINE AND 660 FEET FR	
₩ - -		
THE BAST LINE, SECTION	ON <u>34.</u> TOWNSHIP 9-5 RANGE <u>32 E</u> NMF	M Δ1111111111111111111
	15. Elevation (Show whether DF, RT, GR, etc.)	. 12. County
	4323 Gr.	Lea
^{16.} Check	Appropriate Box To Indicate Nature of Notice, Report or O)ther Data
		NT REPORT OF:
	3063EQUE	NT REFORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	
		ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17. Describe Proposed or Completed Op work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates, includi	
17. Describe Proposed or Completed Op work) SEE RULE 1103.		
17. Describe Proposed or Completed Op work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates, includi permission to plug and abandon per telephone co	
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey.	permission to plug and abandon per telephone co	
17. Describe Proposed or Completed Or work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to	permission to plug and abandon per telephone co	onverstaion with Mr. Joe
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas	permission to plug and abandon per telephone co o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4264	onverstaion with Mr. Joe
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402	permission to plug and abandon per telephone co o total depth of 4265; sing with mud. Spotted cement plug 4131 to 426; 2 to 3490 with 25 sacks. Spotted cement plug 16	5 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1903. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244	permission to plug and abandon per telephone co o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4" above a	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4" above a	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4" above a	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill can Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatio	permission to plug and abandon per telephone co o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1703. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Co	permission to plug and abandon per telephone co o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill can Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatio	permission to plug and abandon per telephone co o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatio Humble Oil & Refining Go Box 1600, Midland, Texas	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1703. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill car Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatio Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1703. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill can Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Cor Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill can Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4" above g on. Sompany s 79701	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatio Humble Oil & Refining Go Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4" above g on. Sompany s 79701	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill can Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatio Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, Texas	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on. Sompany s 79701 ration 79701	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatic Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, Texas	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above g on. Sompany s 79701 s 79701 s 79701 d, Inc., 3900 Lemmon Ave., Dallas, Texas 75219	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatic Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, Texas	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on. Sompany s 79701 ration 79701	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, Texas Adam K. Grafe Associated 18. I hereby certify that the information	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above g on. Ompany s 79701 s 79701 s 79701 d, Inc., 3900 Lemmon Ave., Dallas, Texas 75219 above is true and complete to the best of my knowledge and belief.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, T ex- Adam K. Grafe Associated 18. I hereby certify that the information	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on. Sompany s 79701 ration 79701 s 79701 h, Inc., 3900 Lemmon Ave., Dallas, Texas 75219	onverstaion with Mr. Joe 5 with 25 sacks. 512 to 1700 with 25 sacks. surface zero to 29' with ground level. Fill in
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatic Humble Oil & Refining Go Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, T ex- Adam K. Grafe Associated 18. I hereby certify that the information	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above g on. Ompany s 79701 s 79701 s 79701 d, Inc., 3900 Lemmon Ave., Dallas, Texas 75219 above is true and complete to the best of my knowledge and belief.	5 with 25 sacks. 512 to 1700 with 25 sacks.
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean location Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, T ex- Adam K. Grafe Associated 18. I hereby certify that the information	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on. Sompany s 79701 ration 79701 s 79701 h, Inc., 3900 Lemmon Ave., Dallas, Texas 75219	onverstaion with Mr. Joe 5 with 25 sacks. 512 to 1700 with 25 sacks. surface zero to 29' with ground level. Fill in
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatic Humble Oil & Refining Go Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, T ex- Adam K. Grafe Associated 18. I hereby certify that the information	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in a 4" pipe in surface cement extending 4' above g on. Sompany s 79701 ration 79701 s 79701 h, Inc., 3900 Lemmon Ave., Dallas, Texas 75219	onverstaion with Mr. Joe 5 with 25 sacks. 512 to 1700 with 25 sacks. surface zero to 29' with ground level. Fill in
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill car Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatic Humble Oil & Refining Co Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, T ex Adam K. Grafe Associated 18. I hereby certify that the information signed By Ardan W. A	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above gon. ompany s 79701 ration 79701 is 79701 is 79701 above is true and complete to the best of my knowledge and belief. <u>Mumpun</u> umpun	onverstaion with Mr. Joe 5 with 25 sacks. 512 to 1700 with 25 sacks. surface zero to 29' with ground level. Fill in
17. Describe Proposed or Completed Op work) SEE RULE 1103. April 19, 1968- Verbal 1 D. Ramey. April 20, 1968- Drill to April 21, 1968: Fill cas Spotted cement plug 3402 Spotted cement plug 244 25 sacks. Put piece of cellar and clean locatio Humble Oil & Refining Go Box 1600, Midland, Texas Amerada Petroleum Corpor Box 591, Midland, Texas Superior Oil Company Box 1900, Midland, Texas Adam K. Grafe Associated 18. I hereby certify that the information	permission to plug and abandon per telephone of o total depth of 4265' sing with mud. Spotted cement plug 4131 to 4269 2 to 3490 with 25 sacks. Spotted cement plug 16 to 342 with 25 sacks. Spotted cement plug in s 4" pipe in surface cement extending 4' above gon. ompany s 79701 ration 79701 is 79701 is 79701 above is true and complete to the best of my knowledge and belief. <u>Mumpun</u> umpun	onverstaion with Mr. Joe 5 with 25 sacks. 512 to 1700 with 25 sacks. surface zero to 29' with ground level. Fill in