

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG-5002

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA Oil Producers	8. Farm or Lease Name Mar 679 Ltd. Tr. 2
3. Address of Operator 104 South Pecos, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER "M" 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 10-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Vada-Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4243 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & Abandoned as Follows:

Set CIBP @ 9775' w/2 sx cmt on top  
Cut & pulled 4½" csg @ 5325'  
25 sx @ 5325' (4½" stub)  
25 sx @ 4025' (8-5/8" shoe)  
Cut & pulled 8-5/8" csg @ 904'  
25 sx @ 904' (8-5/8" stub)  
25 sx @ 380' (12-3/4" shoe)  
10 sx @ surface  
Installed dry hole marker per NMOCC regulations  
Plugged & abandoned 11-19-71

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. L. Boyce TITLE Production Clerk DATE 11/29/71  
APPROVED BY John W. Runyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: