NO. OF COPIES RE	DISTRIBUTION  ANTA FE  NEW MEXICO OIL CONSERVATION COMMISSION		Form C-103
			Supersedes Old C-102 and C-103
SANTA FE			Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No.
			K-2588
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIF.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)  1.			7. Unit Agreement Name
OIL X GAS WELL OTHER-			
2. Name of Operator			8. Farm or Lease Name
UNION TEXAS PETROLEUM CORPORATION			State "25"
3. Address of Operator			9. Well No.
1300 Wilco Building, Midland, Texas 79701			10. Field and Pool, or Wildcat
4. Location of Well			- "
UNIT LETTER G , 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM			VIIII (IIII)
THE East LINE, SECTION 25 TOWNSHIP 10-S RANGE 33-F NMPM.			
(Show whether DF, RT, GR, etc.)			12. County
4209' GL			Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABAN	H	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB			
OTHER			
ОТНЕЯ		. 🗀	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.			
1. 13 3/8" Surface casing set @ 367. Cemented w/350 Sxs.,cement circulated.			
2. 8 5/8" Intermediate casing set @ 3998'. Cemented w/525 Sxs., top of cement @ 2420'.			
3. 5½" production casing set @ 9971'. Cemented w/500 Sxs., top of cement @ 7730'.			
	Casing perforations 9917'-9929'		p of cement & 1750 .
	Spotted 50 Sxs. cement plug 9929		·
6. Cut and pulled 4512' 5½" casing, spotted 35 Sxs. cement 100' in 5½" casing stub			
and 100' above.			
7. Spotted 40 Sxs. cement plug @ 4050'.			
8. Cut and pulled 1199' 8 5/8" casing. Spotted 50 Sx. cement plug @ 8 5/8" casing			
stub. 50' in and 50' out.			
9. Spotted 35 Sxs. cement plug @ 50' below & 50' in 13 3/8" casing.			
10. Spotted 10 Sxs. cement plug @ surface and welded on ½" steel plate.			

18. I hereby certify my the information above is true and complete to the best of my knowledge and belief.

SIGNED TITLE Operations Supt.-Western Area DATE March 26, 1971

APPROVED BY TITLE Geologist DATE. 1971

11. Installed dry-hole marker in accordance with regulations.

12. Well P & A 3-24-71.

MAR 20 1971

MARGO MOSTA MESSACO 110 AL