

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.	30-025-22618
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K3905 OG-5846
7. Lease Name or Unit Agreement Name	Peggy Com.
8. Well No.	1
9. Pool name or Wildcat	North Bagley Permo Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4313' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	Tipperary Oil and Gas
3. Address of Operator	800 N. Marienfeld, Suite 100, Midland, TX 79701
4. Well Location	Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line Section 29 Township 11S Range 33E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/1/96 MIRUSU
5/2/96 Circulated 100 bbls. FW. Set 20 SX cement plug at 6900'
5/3/96 Tagged TOC at 6950' with tbq. Circulate hole with mud. Pumped 20 SX cement plug from 6000' to 5698'. Pumped 20SX cement plug from 3780' to 3478'.
5/6/96 Cut casing at 2500' and pulled casing. Pumped 25 sx cement plug from 2550' to 2423'/
5/7/96 Tagged TOC at 2435' w/tbg. Cut csg. & pulled csg. at 700'. Pumped 40 sx cmt plug from 750' to 620'. WOC and tagged TOC at 635'. Pumped 60 sx cement plug from 420' to 318'.
5/8/96 Tagged TOC at 325'. PUH to 60'. Pumped 15 sx cement plug at surface. Welded on plate. Installed surface marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. Jeffrey Sparks TITLE Engineer DATE 5/9/96

TYPE OR PRINT NAME W. Jeffrey Sparks TELEPHONE NO. (915) 683-5203

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE 5/9/96

CONDITIONS OF APPROVAL, IF ANY:

