

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. K-2217	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator Monsanto Oil Company		8. Farm or Lease Name State "K"
3. Address of Operator One First City Center, Ste 1300 Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> , <u>660</u> FEET FROM THE <u>S</u> LINE AND <u>1980</u> FEET FROM THE <u>E</u> LINE, SECTION <u>5</u> TOWNSHIP <u>T10S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Locality <u>Vada Penn</u>
15. Elevation (Show whether DF, RT, GR, etc.) 4252'		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) 8-31-83 Set CIBP @ 9860'.
- 2.) 9-01-83 Set 35 sacks of cement @ 8900'. Mix mud using 10# brine and 25# salt gel per bbl. Circulated hole.
- 3.) 9-02-83 Shot 5½" casing @ 5400'.
- 4.) 9-06-83 Spot 45 sacks of cement @ 5400'. Shot 5½" casing @ 4032'.
- 5.) 9-07-83 Shot 5½" casing @ 3823'.
- 6.) 9-08-83 Spot 60 sacks of cement @ 4062'. Tag plug @ 3811'. Add additional 20 sacks of cement.
- 7.) 9-09-83 Spot 35 sacks of cement @ 2720. Spot 35 sacks of cement @ 2160'. Shot 8 5/8" casing @ 793'.
- 8.) 9-15-83 Spot 65 sacks of cement @ 843. Tag plug @ 665'. Spot 75 sacks of cement @ 400'. Tag plug @ 289'. Spot 10 sacks of cement to top of hole.
- 9.) 9-15-83 Installed Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Regional Production Mgr. DATE 10/4/83

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE AUG 1 1988

CONDITIONS OF APPROVAL, IF ANY: