

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form Approved.
Budget Bureau No. 42-100-105.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Union Oil Company of California

3. ADDRESS OF OPERATOR
c/o Hobbs Pipe & Supply, Box 2010, Hobbs, N. M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980' FSL & 660' FWL

14. PERMIT NO. _____

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4283' GRD

5. LEASE DESIGNATION AND SERIAL NO.
NMC 269264-4

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Newman Federal

9. WELL NO.
25-1

10. FIELD AND POOL, OR WILDCAT
Vada (Penn)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
29-9S-34E

12. COUNTY OR PARISH
Lea

13. STATE
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	(Other) _____

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Propose to spot a 25 sx cement plug on botton @ 9960'.
2. Propose to spot a 25 sx cement plug at 7800'.
3. Propose to spot a 25 sx cement plug at 5 1/2 casing stub @ 6500'.
4. Propose to spot a 25 sx cement plug at top of Glorietta @ 5434'.
5. Propose to spot a 25 sx cement plug at 8-5/8" casing shoe @ 4087'.
6. Propose to spot a 25 sx cement plug at 8-5/8 casing stub @ 3000'.
7. Propose to spot a 25 sx cement plug at 11-3/4 casing shoe @ 383'.
8. Propose to spot a 10 sx cement plug at surface with marker.
9. Hole will be loaded with mud-laden fluids between plugs.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Agent DATE 2/7/72

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
FEB 13 1972

*See Instructions on Reverse Side
L GORDON
DISTRICT ENGINEER