U' TED STATES DEPARTME. OF THE INTERIOR (Other in verse side)

SUBMIT IN TRI CATE*

Form approved. Budget Bureau No. 42-R1424. LEASE DESIGNATION AND SERIAL NO.

re-	5.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

MZ	-0	98	59	1 (-A	÷	٠.	

8. FARM OR LEASE NAME

<u> Mallard-Federa</u>

WELL NO.

GEOLOGICAL SURVEY						
SUNDRY	NOTICES	AND	REPORT	SON	WELLS	

(Do not use this form for proposals to first or to deepen or purchase to a Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME

WELL X

2. NAME OF OPERATOR

Major, Giebel & Forster 3. ADDRESS OF OPERATOR

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

Unit A, 660' FNL, 660' FEL, Sec. 33, T-9-S, R-34-E Lea County, New Mexico

Undesignated

11. sec., t., r., m., or blk. and
SURVEY OR AREA Sec. 33, T-9-S, R-34-E

10. FIELD AND POOL, OR WILDCAT

14. PERMIT NO.

(Other)

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4244 GL, 4256 DF

12. COUNTY OR PARISH 13. STATE New Mexic

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REFORM OF					
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Casing t (Note: Report resu Completion or Reco	ilts of	ALTERI ABANDO & cement	ing well ng casing onment* job etion on Well og form.)	X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinents. proposed work. If nent to this work.) *

Spudded well at 8:00 p.m. Drilled 15" hole to 350'. Cemented 11 3/4" 7/31/68 H-40 ST&C at 350' with 350 sx Type H cement w/2% HA-5.

Plug down at 7:00 a.m. W.O.C. 17 hours. 8/1/68

W.O.C. I hour. Tested casing with 500 psi. OK. Started drilling II" hole 8/2/68 at 1:30 a.m.

Drilled 11" hole to 4050'. Cemented 8 5/8" 24# & 32# J-55 casing at 4050' 8/6/68 with 250 sx Type H cement with 6% gel, plus 150 sx Type H with 2% CaCl. Plug down at 8:30 p.m. W.O.C. 3 1/2 hours.

W.O.C. 15 hours. Tested casing with 1000 psi. OK. Started drilling 7 7/8" 8/7/68 hole at 3:30 p.m.

and correct 18. I hereby certify August Partner TITLE _ (This space for Federal or State office use) DATE TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: