

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HUBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
SEP 10 11 34 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-4-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2728
7. Unit Agreement Name
8. Farm or Lease Name Humble-State
9. Well No. 1
10. Field and Pool, or Wildcat (Simanola Penn) Undesignated
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator K. K. Amini
3. Address of Operator 400 Wall Towers West, Midland, Texas 79701
4. Location of Well UNIT LETTER <u>E</u> , <u>2086</u> FEET FROM THE <u>North</u> LINE AND <u>554</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>10-S</u> RANGE <u>34-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4214 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

8-31-68	Spudded well at 9:00 A.M. Drilled a 15" hole to 383'. Cemented 12-3/4 33.38 # H-40 casing @ 382' with 400 sacks cement. Cement circulated. Plug down @ 6:15 P.M. W.O.C.
9-1-68	W.O.C. total 18-1/2 hours. Tested casing with 600 psi O.K. Started drilling 11" hole @ 1:00 P.M.
9-5-68	Drilled an 11" hole to 4065'. Cemented 8-5/8" O.D. 24# & 32# J-55 casing @ 4065' with 400 sacks cement. Plug down @ 5:30 P.M. W.O.C.
9-6-68	W.O.C. total 18 hours. Tested casing with 1000 psi O.K. Started drilling 7-7/8" hole @ 12:00 noon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Loeen Broom TITLE Agent DATE 9-9-68

APPROVED BY [Signature] DATE SEP 11 1968

CONDITIONS OF APPROVAL, IF ANY:

