

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>OG 4632</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>MGF STATE</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Vada (Penn)</b>
12. County <b>Lea</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator <b>MONSANTO COMPANY</b>
3. Address of Operator <b>101 North Marienfeld, Midland, Texas 79701</b>
4. Location of Well UNIT LETTER <b>E</b> , <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>30</b> TOWNSHIP <b>10S</b> RANGE <b>34E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4226' RKB</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged & abandoned as follows:

Set C.I. Bridge Plug in 5½" Casing at 9880' w/ 35' cement plug on top; displaced hole w/ 10.5# mud.  
Cut 5½" Casing into at 3000' & pulled; bottom 5½" Casing at 10,010';  
Spotted 30 Sx. Cement Plug 3004' - 2904';  
Cut 8 5/8" Casing into at 1210' & pulled; bottom 8 5/8" casing 3972';  
Spotted 43 Sx. Cement Plug 1210' - 1110';  
Spotted 55 Sx. Cement Plug 360' - 260'; bottom 11 3/4" 410';  
Spotted 10 Sx. Cement Plug 12' - surface;  
Welded plate over 11 3/4" & installed dry hole marker;  
Plugging complete 5/12/72.

You will be notified when lease is cleaned up and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *D. W. Wood* TITLE District Production Mgr. DATE 1/31/73  
APPROVED BY *John W. Rung* TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: