

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Ralph Lowe		8. Farm or Lease Name Speight
3. Address of Operator P. O. Box 832, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> , <u>510</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>7</u> TOWNSHIP <u>9-S</u> RANGE <u>35-E</u> NMPM.		10. Field and Pool, or Wildcat Vada (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4203 GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well to be plugged as per verbal instructions of Mr. Joe Ramey as follows:

Cast Iron Bridge Plug @ 9750' with 4 sax cement on top of plug; 50 sacks of cement in and out of stub of 5-1/2" casing to be shot off @ approximately 4500'; 50 sacks cement in and out of 8-5/8" at 4060'; 10 sacks @ surface w/regulation marker. Drilling Mud to be used between cement plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Tom Murray TITLE Agent DATE 3/21/72

APPROVED BY Joe D. Ramey TITLE Dist. 1, Supv. DATE MAR 23 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 23 1972

OIL CONSERVATION COMM.
HOBBS, N. M.