

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH
	13. STATE

NM-361

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Allyn 687 Ltd.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Vada-Penn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 9, T-9-S, R-36-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set CIBP @ 9800' w/3 sx cmt. on top.
Cut & pull 5-1/2" csg.
Set 50 sx cmt. @ stub.
Set 50 sx cmt. @ 5539' (Glorietta).
Set 50 sx cmt. @ 4115' (Base Intermediate).
Cut & pull 8-5/8" csg.
Set 50 sx cmt. on 8-5/8" stub.
Set 50 sx cmt. @ 375' (Base Surface).
Set 10 sx cmt. @ surface.
Install dry hole marker.

Amendments:

1. Place additional 25 sack cement plug inside 5" csg. in interval 7800 to 8000 feet or CIBP at 7900 feet with cement cap.
2. Cement caps on bridge plugs should be 35 feet in length.
3. Mud to be placed between plugs.

APPROVED SUBJECT TO POSSIBLE FUTURE
REQUIREMENT THAT PAD AND/OR ROAD
BE RIPPED AND RELEVELLED

18. I hereby certify that the foregoing is true and correct

SIGNED Janie Jones
(This space for Federal or State office use)

TITLE Production Clerk

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
AS AMENDED
JUL 5 1974
ARTHUR R. BROWN
DISTRICT ENGINEER

DATE 7/2/74

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.