

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ GAS ☐ WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. N.M. 058311-A
2. NAME OF OPERATOR ETA Oil Producers		6. IF INDIAN, ALIEN, OR TRIBE NAME
3. ADDRESS OF OPERATOR 104 S. Benson Midland, Texas 79701		7. UNIT AGREEMENT NAME Reservoir 686 Ltd.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' ESL & 1980' FWL		8. FARM OR LEASE NAME
14. PERMIT NO.		9. WELL NO. Vada-Parr
15. ELEVATIONS (Show whether on, at, or below surface) 4230' E. on		10. FIELD, AND-POOL, OR WILDCAT
		11. SEC., T., R., M., OR BLK. AND Sec. 6, T. 1 N., R. 35 E.
		12. COUNTY OR PARISH Lea, New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☒
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Proposed Procedure:

**Call USGS Hobbs (505/393-3612) 24 hrs. advance.
Hole to be filled w/mud laden fluid.**

**Lay down 2" tbg w/Model "R" pkr & jet pump
Set GIBF @ 9700' W 3" sx cmt. on top.
Cut & pull 5-1/2" csg. T/C @ ± 8200'.
Set 50 sx cmt. @ stub.
Set 50 sx cmt. @ 5424' Glorietta
Set 50 sx cmt. @ 4010' Base intermediate.**

35' cement plug

**Cut & pull 8-5/8" csg.
Set 50 sx cmt. on 8-5/8" stub.
Set 50 sx cmt. @ 381 Base surface.
Set 10 sx cmt. @ surface.**

Install dry hole marker.

18. I hereby certify that the foregoing is true and correct

Production Clerk

11/14/72

SIGNED

James Jones

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

**APPROVED
AS AMENDED
11/17/72**

[Signature]

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between, and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

847-485

RECEIVED

NOV 21 1963

OIL CONSERVATION COMM.
WASHINGTON, D. C.