

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-23105
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Cheyenne Resources
3. Address of Operator P.O. Box 1813 Midland, Texas 79702

7. Lease Name or Unit Agreement Name Vada Pruitt
8. Well No. 1
9. Pool name or Wildcat Vada-Penn

4. Well Location Unit Letter L : 2130' Feet From The South Line and 660' Feet From The West Line Section 14 Township 9S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4,116.5 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) CIBP +35 sx. 9700'
- (2) Load hole w/10# brine w/25# SWG per barrel
- (3) 100' plug @ 6200' inside 4½" csg. or 50'in-50'out on 4½" stub plug
- (4) 100' plug 50' in-50' out on 4½" stub plug if csg. not cut @ 6200'
- (5) 100' 8-5/8" shoe plug 4080-3980 ***TAG***
- (6) 100' 50' in-50' out on 8-5/8" stub plug
- (7) 100' 13-3/8" shoe plug 430'-330'
- (8) 20 sx. surface plug w/dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frelan Fields TITLE Agent DATE 12/7/92
(915)
TYPE OR PRINT NAME Frelan Fields TELEPHONE NO. 366-1852

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

DEC 08 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: