NO. OF COPIES RECEIVED			
DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE			
OPERATOR			
	SLINIDE		

Form C -103

SANTA FE FILE NEW MEXICO OIL CONSERVATION COMMISSION C. C. E. NEW MEXICO OIL CONSERVATION COMMISSION C. C. E. NEW MEXICO OIL CONSERVATION COMMISSION C. C. E. SUNDRY NOTICES AND REPORTS ON WELLS OFFICE OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS ON NOT LES THIS CONSERVATION FROM LAW FOR STATE OF THE CONSERVATION COMMISSION	DISTRIBUTION			HUDHS BEELL	Supersede			
UNS.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (So Not use this for the product of the p	SANTA FE	NEW N	EXICO OIL CON	ISERVATION COMMISSION E. O.	C. C. Effective			
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS PROPERTY OF FEMALE PROPERTY OF THE PROPE	FILE							
SUNDRY NOTICES AND REPORTS ON WELLS (SO NOT USE THE PROPERTY OF PERMIT AND PROPERTY OF SUBSECUENT RESERVOIR. 1. Common of Operator BTA 0il Producers 1. Address of Operator 1. Address of Operator West	U.S.G.S.			OU 0 12 42 AM	\$6 5a. Indicate T	ype of Lease		
SUNDRY NOTICES AND REPORTS ON WELLS CONTROL CONTROL	LAND OFFICE				State X	Fee		
Co Not use this format is many notices and reports on wells Co Not use this format is many notices and reports on wells	OPERATOR				5. State Oil &			
SUNDRY NOTICES AND REPORTS ON WELLS OIL A SASSE OF A STATE OF THE PROPERTY OF THE STATE OF THE SECTION OF THE STATE OF TH					1			
The State of Coperators 2. Nome of Operator BTA 01 Producers 1. Address of Operator 1. Address of		SUNDRY NOTICES AND) PEPOPTS OF	JWELLS	777777	mmmil		
The State of Coperators 2. Nome of Operator BTA 01 Producers 1. Address of Operator 1. Address of	(DO NOT USE TH	S FORM FOR PROPOSALS TO DRILL OR USE "APPLICATION FOR PERMIT - "	TO DEEPEN OR PLUG	N WELLS BACK TO A DIFFERENT RESERVOIR.				
. Name of Operator BTA 011 Producers . Name of Operator BTA 011 Producers . Address of Operator BTA 011 Producers . 104 So. Pecos, Midland, Texas 79701 . 10. Location of Well Unit Letter E . 1980 Pect from the North Line and 660 Feet from Undesignated. The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E NAME The West Line, section 2 Yownship 9-S AANGE 35-E The West Line, section 2 Yownship 9-S AANGE 35-E The West Line, section 2 Yownship 9-S AANGE 35-E The West Line, section 2 Yownship 9-S AANGE 35-E The West Line, section 3 Younship 3 The We	·•		OKE C-TOTY FOR SC	CH PHOPOSALS.)	7 Unit Agrees			
Example of Operators BTA 011 Producers 1. Address of Operator 1. Address of Operator 1. Address of Operator 1. Address of Operator 1. Location of Well 1. Location of Well		· ·			7. Ont Agreen	nent Name		
Address of Operators 104 So. Pecos, Midland, Texas 79701 105 Fleid and Pool, or Wild Undesignated. 106 Pett from the West Line, section 2 Township 9-S NAMEE 35-E NAMEM. 115. Elevation (Show whether DF, RT, GR, etc.) 12. Ceumty 12. Ceumty 12. Ceumty 12. Ceumty 13. Elevation (Show whether DF, RT, GR, etc.) 12. Ceumty 12. Ceumty 13. Elevation (Show whether DF, RT, GR, etc.) 14157' G.J. Lea 12. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 13. Elevation To: 14. Subsequent Report of: 14. Subsequent Report of: 15. Elevation (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 17. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 18. Elevation (Show whether DF, RT, GR, etc.) 19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 18. Elevation (Show whether DF, RT, GR, etc.) 19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: 19. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of Other Data Subsequen	2. Name of Operator							
1. Address of Operator 104 So. Pecos, Midland, Texas 79701 105. Well No. Pecos, Midland, Texas 79701 115. Fleid and Fool, or Wild Undesignated. THE West LINE, SECTION 2 TOWNSHIP 9-S RANGE 35-E NAME. 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea Notice of Intention to: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: CERTORIA REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PRILLING OPRS. COMMENCE ORILLING OPRS. CASHIE TEST AND CEMENT JOB X OTHER OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1 103. 5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55. ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-1 WOC.								
104 So. Pecos, Midland, Texas 79701 1	BTA U11 Producers 3. Address of Operator				Cap 692	Cap 692 Ltd.		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: CHANGE PLANS CASING TEST AND CEMENT JQB OTHER CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER CHANGE PLANS CASING TEST AND CEMENT JQB ALTERING CASING CHANGE PLANS CASING TEST AND CEMENT JQB ALTERING CASING COMMENCE OBILLING OFN. CASING TEST AND CEMENT ALTERING COMMENCE OBILLING COMMENCE OBILLIN	•				9. Well No.			
UNIT LETTER E 1980 PEET FROM THE NORTH LINE AND 660 PEET FROM Undesignated. THE West LINE, SECTION 2 TOWNSHIP 9-S HANGE 35-E NAMPH. 15. Elevation (Show whether DF, RT, GR, etc.) 4157' G.L. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: REMEDIAL WORK COMMENCE DRILLING DRNS. CASING TEST AND CEMENT JOB NOTHER OTHER Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1103. 5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55. ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-1 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	Location of Wall	ecos, Midland, Tex	<u>cas 7970]</u>		1			
THE West LINE, SECTION 2 TOWNSHIP 9-S RANGE 35-E NAPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4157' G.L. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CHANGE DRILLING OPNS. CHANGE PLANS CHANGE DRILLING OPNS. CHANGE PLANS COMMENCE DRILLING OPNS. CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER 1. DESCRIBE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1703. 5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55. ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-2 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min					10. Field and	Pool, or Wildcat		
THE West LINE, SECTION 2 TOWNSHIP 9-S RANGE 35-E NAPM. 15. Elevation (Show whether DF, RT, GR, etc.) Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK SUBSEQUENT REPORT OF: CHANGE PLANS COMMENCE DRILLING OPNS. CHANGE PLANS CHANGE DRILLING OPNS. CHANGE PLANS COMMENCE DRILLING OPNS. CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X OTHER COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X ALTERING CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X ALTERING CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X ALTERING CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X ALTERING CASING COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB X ALTERING TEST AND CEMENT JQB X ALTE	UNIT LETTERI	1980 FEET FROM	North	LINE AND 660	Jndesia	nated		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK CHANGE PLANS OTHER Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1703. Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-2 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min					777777	milli		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK TEMPORABILY ABANDON CHANGE PLANS	THEWest	LINE, SECTION 2	OWNSHIP 9-5	35-E				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. COMMENCE DRILLING ALTERING CASING COMMENCE DRILLING COMMEN				NANGE N	MPM. (
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. COMMENCE DRILLING ALTERING CASING COMMENCE DRILLING COMMEN		15. Eleva	tion (Show whether	DF, RT, GR, etc.)	12. County	~,/////////		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER CHANGE PLANS CASING TEST AND CEMENT JQB CHANGE PLANS CASING TEST AND CEMENT JQB CHANGE PLANS CASING TEST AND CEMENT JQB COMMENCE DRILLING OPNS. CASING OPNS. CASING OPNS. COMMENCE DRILLING OPNS. CASING OPNS. CASING OPNS. CASING OPNS. CASING OPNS. CASING O			41571	CT	1			
SUBSEQUENT REPORT OF: REFORM REMEDIAL WORK EMPORABILLY ABANDON ULL OR ALTER CASING OTHER Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1703. 5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-2 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min.	5.	Chook Appropriate Pe			ьеа	<u> </u>		
SUBSEQUENT REPORT OF: ERFORM REMEDIAL WORK EMPORABILLY ABANDON OTHER OTHER Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1703. 5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held 0 Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-2 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	.	Check Appropriate Box	10 Indicate I	Nature of Notice, Report or	Other Data			
Commence or Drilled 17½" hole to 382'. R. Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-20 woc. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min.	NC	TICE OF INTENTION TO:				₹:		
Commence or Drilled 17½" hole to 382'. R. Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-20 woc. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min.								
OTHER CHANGE PLANS CASING TEST AND CEMENT JQB X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB X CHANGE PLANS CASING TEST AND CEMENT JQB X CHANGE PLANS CASING TEST AND CEMENT JQB X CHANGE PLANS CASING TEST AND CEMENT JQB X CASING TEST AND CEMENT JQB CASING TEST	ERFORM REMEDIAL WORL	PLUG	AND ABANDON	REMEDIAL WORK	ALT	ERING CASING		
OTHER CHANGE PLANS CHANGE PLANS OTHER OTHER OTHER CASING TEST AND CEMENT JQB X OTHER OTHER OTHER OTHER DYNAM DYNAM DYNAM CASING TEST AND CEMENT JQB X OTHER OTHER OTHER OTHER OTHER CASING TEST AND CEMENT JQB X OTHER OTH	EMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG	AND ABANDONMENT		
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1703. 5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	ULL OR ALTER CASING	CHAN	GE PLANS	CASING TEST AND CEMENT JOB				
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1703. 5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min				OTHER		[-		
5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	OTHER							
5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	•							
5-27-69: Spudded in 10:45 A.M. 5-27-69. Drilled 17½" hole to 382'. R. 12-3/4" O.D. 33.38# surface casing - set @ 382' w/375 sx reg. 2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	Describe Proposed o work) SEE RULE 11	Completed Operations (Clearly states)	e all pertinent det	ails, and give pertinent dates, includ	ding estimated date o	f starting any proposed		
2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held 0 Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	,							
2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held 0 Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	5-27-69:	Spudded in 10:45	A.M. 5-27	-69 Drilled 175"	holo +o 20	221 - 22-		
2% c.c. Cement circ. Plug down 5:30 P.M. 5-27-69. WOC. 5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min		12-3/4" O.D. 33 3	8# surfac	e casing - set @ 2	021 11/275	oz. Kan		
5-28-69: After WOC 18 hrs., pressure tested casing to 600 psi - Held O Now drilling ahead. 5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min		2% C C Cement of	ira Dlu	a down 5.30 P. M. T	02 W/3/5 S	sx reg.		
5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min		2/0 C.C. Cement C	iic. Piu	g down 5:30 P.M. 5	-27-69. W	DC.		
5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	5-28-60-	After Wood 10 har-		- 414 7				
5-31-69: Drilled 11" hole to 4060'. Ran 8-5/8" O.D. 24, 28 & 32# J-55 ST&C casing set @ 4060' w/400 sx cement. Plug down 7 P.M. 5-3 WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	J-40-09:	Marianillia -	, pressur	e tested casing to	600 psi -	Held O.K.		
WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min		Now drilling ahea	a.					
WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	E 23 62							
WOC. 6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min	5-31-69:	Drilled 11" hole	to 4060'.	Ran 8-5/8" O.D.	24, 28 & 32	?# J-55,		
6-1-69: After WOC 18 hrs pressure tested casing w/1200# for 30 min		ST&C casing set @	4060' w/	400 sx cement. Pla	ug down 7 F	$^{\circ}$.M. $5-31-69$		
Probate concea caping wrizing from 10 min		WOC.			_			
Probate concea caping wrizing from 10 min								
probbate cobced caping w/1200# 101 30 min	6-1-69:	After WOC 18 hrs.	- pressu	re tested casing w	/1200# for	30 min		
aneau.		Held O.K. Now dr	illing ah	ead	/ 1200# TOF	oo min.		
			ing ain	suu.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	I hereby certify that #	information above is terms and	nlete to the tri		· · · · · · · · · · · · · · · · · · ·			
nowheater and complete to the best of my knowledge and belief,	/ 75	and com	piece to the best of	my knowledge and belief.				
	(////				•			
TITLE Drilling Manager 6-4-69	IED	Ministell Comment	TITLE	Drilling Manager	DATE 6-	4-69		