

STATE OF NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE

BRUCE KING GOVERNOR February 3, 1993

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

M&G Oil Inc.
P.O. Box 957
Crossroads, NM 88114
Gentlemen:
Form C-103, Report of Plugging, for your ANDERSON A #1-D Sec 9, T9S, R35E
Lease Well # Unit S-T-R cannot be approved until a Division representative has made an inspection of the location and found it to be cleared to comply with Division Rules and Regulations. Please check each item in the space provided to indicate that the work has been done.
() 1. All pits have been filled and levelled.
() 2. Rat hole and cellar have been filled and levelled.
() 3. A steel marker 4" in diameter and approximately 4' above ground level as been set in concrete. It must show the <u>Operator</u> , <u>Lease Name</u> , <u>Well Number</u> , <u>Quarter/Quarter Section or Unit Designation</u> , <u>Section</u> , <u>Township and Range</u> numbers which have been permanently stenciled or welded on the marker.
() 4. The location has been levelled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
() 5. The dead men and tie downs have been cut and removed.
() 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been levelled and cleared of all junk and equipment.
The above are minimum requirements and no plugging bond will be released until all locations for plugged and abandoned wells have been inspected and Forms C-103 approved. When all of the work outlined above has been done, please notify this office by filling in the blank form below and retuning this letter to us so that our representative will not have to make more than one trip to the location.
OIL CONSERVATION DIVISION
June Santon
Jerry Sexton, Supervisor Dist I
FILL IN BELOW AND RETURN
I certify that the above work has been done and the $$\tt LEASE = \tt WELL \# UL-S-T-R = \tt LEASE = \tt WELL \# UL-S-T-R = \tt LEASE = \tt WELL \# UL-S-T-R = \tt LEASE = \tt$
OPERATOR