

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-23209
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRIY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name S. F. Anderson "A"
2. Name of Operator M & G Oil, Inc.	8. Well No. 1
3. Address of Operator P.O. Box 957 Crossroads, NM 88114	9. Pool name or Wildcat Vada-Penn
4. Well Location Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 9 Township 9S Range 35E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4175 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) CIBP +35 sx. 9700'
- (2) Load hole w/10# brine w/25# SWG per barrel
- (3) 100' plug @ 6200' inside 5½" csg. or 50' in 50' out 5½" stub plug
- (4) 100' plug 50' in 50' out 5½" stub plug if csg. not cut @ 6200'
- (5) 100' 8-5/8" shoe plug 4114'-4014' ***TAG***
- (6) 100' plug 50' in 50' out 8-5/8" stub plug
- (7) 100' 13-3/8" shoe plug 415'-315'
- (8) 20 sx. surface plug w/dry hole marker

THE COMMISSION MUST BE NOTIFIED 30 DAYS PRIOR TO THE DATE OF ANY OPERATIONS TO BE APPROVED FOR THE C-103

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE Agent DATE 12/7/92
(915)
TYPE OR PRINT NAME Frelan Fields TELEPHONE NO. 366-1852

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DEC 09 '92

APPROVED BY _____ DISTRICT _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: