

to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Diaz Rd., Aztec, NM 87410

Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL NO.	30-025-23247
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Pearl Marr
8. Well No.	1
9. Pool name or Wildcat	Sawyer, West (SA)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☐	OTHER WELL ☐	OTHER ☐	SWD ☐
2. Name of Operator	Coastal Oil & Gas Corporation			
3. Address of Operator	P. O. Box 235, Midland, Texas 79702			
4. Well Location	Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line			
Section	33	Township	9-S	Range
			37-E	NMIM
10. Elevation (Show whether LF, RKB, RT, GR, etc.)		Lea County		
4003' (KB)				

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	☐	PLUG AND ABANDON	☐
TEMPORARILY ABANDON	☐	CHANGE PLANS	☐
PULL OR ALTER CASING	☐		☐
OTHER:			

SUBSEQUENT REPORT OF:

REMEDIAL WORK	☐	ALTERING CASING	☐
COMMENCE DRILLING OPNS.	☐	PLUG AND ABANDONMENT	☐
CASING TEST AND CEMENT JOB	☐		
OTHER:	Convert to SWD & change lease name from Marr #1 ☒		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Convert to SWD well per Order Number SWD-372.

10-27-92 MIRU. POOH and LD rods and production tubing. PU AD-1 packer and Duolined tbg,
thru GIH. Set packer at 4907', pressure up on casing, leaking by packer. Packer would
11-2-92 not hold. POOH. GIH with RBP and RTTS, set RBP at 4908', tested to 1000#, OK.
Pressure casing to 200#, OK. Discussed with Jerry Sexton, got OK for 200# chart.
POOH with RBP and RTTS. GIH with Model "R" Double Grip packer on lined tbg.
Set pkr at 4905'. Load hole with packer fluid, press csg to 380#, dropped to
365# in 30 minutes. Prep to commence injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bobby L. Smith TITLE Sr. Petroleum Engineer DATE 11-3-92
TYPE OR PRINT NAME Bobby L. Smith TELEPHONE NO. 915-682-7925

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

DATE

NOV 05 '92

RECEIVED

NOV 04 1992

OCD HOBBS OFFICE

