

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
3. Address of Operator	9. Well No.
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER _____, _____ FEET FROM THE _____ LINE AND _____ FEET FROM _____	11. Field and Pool, or Wildcat
THE _____ LINE, SECTION _____, TOWNSHIP _____, RANGE _____, NMPM.	12. County
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.

Notes:
12-3/4" set 2' circulated w/ cut.
2-5/8" set 450' w/ 15 sacks cement
4-3/8" set 100' w/ 15 sacks cement
Perfor. 100' to 110'.

Release of well and abandon as follows:

Set 100' + 15 sacks cement or 35' cement or 35'
Set 100' + 15 sacks cement casing cut-off
Set 100' + 15 sacks cement 550' to 540' if cas. recovered below Marietta
Set 100' + 15 sacks cement base of 8-5/8" cas.
Set 100' + 15 sacks cement 8-5/8" stub
Set 100' + plug 12-3/4" Surface Casing base
Set 100' + plug surface install dry hole marker
Note All plugs will be set w/ hole circulated w/ salt water mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE Agent DATE 10-21-64

APPROVED BY _____ TITLE _____ DATE _____
Orig. Signed by Joe D. Ramey Dist. 1, Supv.

CONDITIONS OF APPROVAL, IF ANY: