

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Natural Energies, Inc.	8. Farm or Lease Name Lario State
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240	9. Well No. #1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>510</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> N.M.P.M.	10. Field and Pool, or Will not Bar U Penn
15. Elevation (Show whether DF, RT, GR, etc.) UK	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25 sx plug to cover existing perforations, 9150/9160'.
2. Loaded hole w/mud-laden fluids.
3. Spotted a 35 sx plug @ casing stub, approx. 4800'.
4. Spotted a 45 sx plug in and out of base of 8-5/8 intermediate, 3626'.
5. Spotted a 75 sx plug @ stub of 8-5/8 casing, approx. 1000'.
6. Spotted a 75 sx plug in & out of base of 11-3/4, 376'.
7. Spotted a 10 sx plug @ surface & erected a 4" regulation marker.
8. Well was plugged & abandoned on 5/17/73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stanley Sarker TITLE Agent DATE 5/30/73

APPROVED BY William E. Kegg TITLE Commissioner DATE 5/30/73

CONDITIONS OF APPROVAL, IF ANY: