

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-23353</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. OG-6008
7. Lease Name or Unit Agreement Name State "E"
8. Well No. 1
9. Pool name or Wildcat <u>Perm</u> N. Bagley, Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4318 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Read & Stevens, Inc.
3. Address of Operator P.O. Box 1518, Roswell, NM 88202	4. Well Location Unit Letter <u>N</u> : <u>2093</u> Feet From The <u>West</u> Line and <u>660</u> Feet From The <u>South</u> Line Section <u>7</u> Township <u>11S</u> Range <u>33E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 9,400'. Perf Wolfcamp @ 9,176-9,180, 8,658-8,667, 8,645-8,649, & 8,601-8,605. Acidize w/1,750 gal 20% NEFE acid, AIR=3.2 BPM @ 4,800 psi. Swab dry, w/small trace of oil. RDMOPU 4/13/90. Evaluate for P & A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Maxey, Jr. TITLE Petroleum Engineer DATE 4-17-90
TYPE OR PRINT NAME John C. Maxey, Jr. TELEPHONE NO. 505/622-3770

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR TITLE DATE
CONDITIONS OF APPROVAL, IF ANY:

APR 19 1990

RECEIVED

APR 18 1990

OCD
MOBBS OFFICE