

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-6008

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Charles B. Read	8. Farm or Lease Name State "E"
3. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>2093</u> FEET FROM THE <u>West</u> LINE, SECTION <u>7</u> TOWNSHIP <u>11S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat N. Bagley L. Penn (undesig)
15. Elevation (Show whether DF, RT, GR, etc.) 4318' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-13-69: Ran 89 jts of 8 5/8", 24# & 28#, J-55 Csg. 3728.50' set @ 3720' RKB. Cmt w/250 sx class H w/2% Gel & 8# salt, followed by 100 sx class H w/2% CaCl₂ and 8# salt per sx. Plug down @ 4:37 P.M. Press test to 1500 PSI for 30 min. Test OK. WOC for 18 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Charles B. Read</u>	TITLE <u>Agent</u>	DATE <u>11-17-69</u>
APPROVED BY <u>Leslie A. Clement</u>		
CONDITIONS OF APPROVAL, IF ANY:		